



SEGA OF AMERICA, INC.
Consumer Products Division

Rex Sabio
242


32X Technical Information

Doc # MAH-41-RS-090894

© 1994 SEGA. All Rights Reserved.

32X Technical Information

- 1 The following modifications are necessary when a Mega Drive 32 Mbit SRAM board is used with the 32X.




- The following modifications are necessary when a Mega Drive 16 Mbit SRAM board is used with the 32X.



Work Procedure

1. Lift no. 1 pin of U31 and U32.
2. Similarly, lift no. 13, 14, and 15 pins of U33.
3. Jump the no. 14 pin of U30 and the no. 13 and 14 pins of U33.
4. Connect the no. 15 pin of U33 to the GND (no. 8 pin).
5. Jump the no. 9 pin of U33 to each no. 1 pin of U31 and U32.

After Modification



Operation cannot be guaranteed if U31 and U32 are not AC or ALS type.
If equipped with the LS type, the AC or ALS type should be attached, replacing the LS type.



3. The following modifications are necessary when a Mega Drive 32 Mbit ROM board is used with the 32X.



Work Procedure

1. Cut between the pattern of the IC13 no.1 pin and the through-hole below the pin.
2. Cut between the pattern of the IC14 no.1 pin and the through-hole to the left of the pin.
3. Cut the trace pattern of the IC15 no.1 and no.4 pins.
4. Wire (connect) IC15 no.1 pin, IC14 no.1 pin, and IC13 no.1 pin.
5. Wire (connect) the IC15 no.8 and no.9 pins to B16 of the card edge.
6. ICE must not be reset when in the break condition.
It should be reset while the go command is being executed.
If ICE is reset in the break condition, it will not operate when the power is turned on.
7. The 32X target Vop.2.0 does not operate unless SP12 is cut 2.3 or greater and the RT version is 3.21 or greater.
8. If doing VRESET with the RV bit equal to 1, it will not restart if the power is turned off. See Technical Information No. 1 for more information.
9. The RV bit should be equal to 1 when reading and writing to the FRAM. Normally it is not possible to read and write when the RV bit is equal to 0. The RV bit is irrelevant when reading and writing to the SRAM.

8. Development equipment is not required when using the bank IC, but initialization by software must be done due to cross-operations by the sample cartridge

(8/1/94)

Specifically, after the power is turned on

ldr	\$(A180F1,a1)	:	bank dummy read
strb	(a1)	:	
moving	#0, d0	:	do \$20000 ~ \$2FFFF in ROM
movne.w	#02700, sr	:	set in stop interrupt condition
pr	Bank1cst	:	addressed to 0 (routine within Vector ROM)
movne.w	#02000, sr	:	Return SR to origin if required

Implement corrective measures with respect to the super 16 Mbit software whether or not a bank IC is used due to the structure (design) of the commercial cartridge (not required with 16 Mbit = backup)

9. All 68000 interrupts must be prohibited during the period that the KY bit = 1
10. Initialization of the done run timer must be done whether or not interrupt is used in coping with SH2 interrupt
11. Concerning versions of the MD1/F chip

Chip No Development target

315-5780	Ver. 1.0	Bug in FWML chip must be exchanged
315-5818	Ver. 2.0A	Speed limit low
315-5818A	Ver. 2.0A	Speed is fast

5818 and 5818A are mixed in the product.

With respect to 5818, as errors seldom occur in SH2 - 68000 communication, please use 5818A-loaded target/product in final check.

12. About ROM read when KY = 1

The following address data is not normally read when KY = 1

\$1070 ~ \$1073 (4 bytes)
 \$2070 ~ \$2073 (4 bytes)
 \$3070 ~ \$3073 (4 bytes) (total 12 bytes)

13. When a CD is used, Word-RAM-to-VRAM-copy-on-DMA has a problem in the timing of data fetch, and since data becomes undefined, it can not be used
14. In the 32X VDP, the shift bit becomes invalid when the lower byte of the base address set in the line table is \$FF. Therefore, make sure the lower byte in the table is not \$FF when using shift



15. In the current (Aug. 15, 1994) target version 2.0A, the 68000 locks up when Z80 accesses the 68000 area. Revision is required to develop a program in which Z80 accesses the 68000 area.

With target version 2.0B (contains corrective measures to the above problems concerning version 2.0A), version 2.1 (scheduled for Sept. 1994), and their products, the problems above are solved but the following limitation is added:

Writing to \$040000 - \$04FFFF as well as the \$A15000 - \$A153FF area by the Z80 causes the 68000 to lock up; therefore, in such cases do not write by the Z80 (read is okay). The MD-work RAM and PSC can be written to.

16. About target Version 2.1

Target version 2.1 (scheduled for Sept. 1994) performs corrective action no. 6 VRIES in this document. Z80 corrective action of no. 15 is performed. The NMI of each CPU is collected and wired to one spot.

17. Regarding SIX development board security release

SIX development board starts up from 68000 side boot ROM when power is switched on. As a result, when power is on, R/W against cartridge connector is not allowed. To avert this, make sure to write 1 using 1 byte to \$A14100. GENESIS-OS will be released, and the normal access will be allowed.

18. (1/22/94)

For EPROM, please use those with access time 120 nsec or less. Specifically make sure the T_{acc} and T_{cc} catalog values are 120 nsec (MAX) or less (this should be a condition).

Major Makers' model number examples

Toshiba	16M	16-bit bus	21C076800D-120
	4M	16-bit bus	20C06800D-120
NEC	4M	8-bit bus	μPD07C400D-120

19. (8/25/94)

Only word unit-based access is allowed from SH2 to PWM Lch pulse width register (20004034H), Rch pulse width register (20004036H), and MONO pulse width register (20004038H). The byte unit-based access is prohibited.

With respect to PWM control register and period (cycle) register, the byte unit-based access is allowed.

From the 68000, with respect to each pulse width register, the byte unit-based access is allowed by writing in order of the upper byte and the lower byte.

In target ver 2.0a development board, compared to FM sound source, PWM sound volume has become fairly small. Please add the following modification. The volume products have already been modified. Some working samples have not yet been modified. The target ver 3.0 (the next development target scheduled for the end of September) has already been modified.

Modification: Change R71 and R72 from 3 KΩ to 10 KΩ.

Through the above measures, the balance between FM sound source and PWM sound source is improved. However, please note that by *maximizing* both sound sources, the sound after mixing becomes distorted. After mixing, set the both sound source volumes so that the sound is not distorted. Also, with PWM sound source, please note that because of a wider dynamic range over the FM sound source, the sound at peak time tends to get distorted when setting through an average sound volume.

21. Following target ver 3.0, WS, the volume product uses a different decoder and filter compared with target ver 2.0a. As a result, the screen display is somewhat different. Following target ver 3.0, WS, the volume product, WS, compared with ver 2.0a, has the following features:

1. Colors are somewhat more vivid
2. Less blur (filar) in the picture.

Make the final graphics check, after target ver 3.0, using WS, volume product.

22. When Z80 accesses PSG, make sure that bank settings at access time are values outside the 500000-53FFFFF and 5940000-59FFFFF ranges.

After Z80 accesses PSG, the MegaDrive internal circuitry bank automatically becomes \$C0000a. However, after the Z80 access is over, the currently set bank values will be output to the 68000 side, and here, there will a period of time existing during which the signal that displays occurs on the 68000 side will be in an active mode.

With MegaDrive, there would be no problem; however, 32X compared to 68000 has a much less restriction. Therefore, it would react to the above state, and if bank settings are in the 500000-53FFFFF and 5940000-59FFFFF ranges, 32X will misunderstand that access to the adapter has occurred. And soon after 68000 accesses this area, this misunderstood data could be passed to 68000. In addition, depending on the address at that time, the contents of 32X registers could be damaged.

Also, please note that because this phenomenon could occur at very different frequencies depending on the MegaDrive individual differences, the problem may not occur when the software is being checked.

